



Repairs and Swing Replacement

Henley-In-Arden

February 2021 - V1

Repairs and Swing Frame



Repair agreed issues on existing towers



Replace swing frame with new. Keep fixings but install new swings (type tbc)

Breakdown of Costs



Quantity	Description of Works	Total ex VAT
1	Repair split/missing timbers on Tower	£295.00
1	Install new swing frame (<i>dispose of old</i>)	£865.00
1	2 x New Swing Seats	£120.00
Total cost, ex VAT		£1,280.00